#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001364

Address: 333 Burma Road Date Inspected: 29-Dec-2007

City: Oakland, CA 94607

**OSM Arrival Time:** 1300 **Project Name:** SAS Superstructure **OSM Departure Time:** 2200 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No N/A **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A

**Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** N/A

## **Summary of Items Observed:**

(Sent off island at 1830 due to weather and only worked on reports and showed Gabe how to do some of the partial penetration ultrasonic testing.)

### **Summary of Conversations:**

No conversations held today.

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

**Inspected By:** Berger, Bruce Quality Assurance Inspector **Reviewed By:** Cochran, Jim **QA** Reviewer